

Extra Large Display

Humidity

0-100%

Temperature

-30 to 80°C



Extra Large Display of Temperature and Humidity Indicator to monitor the parameters of temperature & humidity in critical applications like :

Cold storage, Cold chains, Food, Pharmaceuticals, bio-medical, logistics, Warehouses, Airports, **Hospitals**, Machinery Rooms, Ship-Building, IT Server Rooms, Data Center ,cold storage, cold chains, **Pharmaceuticals**, bio-medical, logistics, Warehouses, **Hospitals**, Machinery Rooms, Ship-Building, Operation Theaters, ICU etc with real time **Data logger**